

SERVICE ANALYSIS DASHBOARDS


Active Service Count TODAY: 0 MTD: 30 YTD: 73	Service Trend Per DAY: 1.5000 Per MONTH: 10.4286 Per YEAR: 0	Service Creation/Completed TODAY: 0 THIS WEEK: 5 THIS MONTH: 30 THIS YEAR: 73	Invoice Pending Services COUNT: 10 AMOUNT: 30	Service Count /Invoice Raised COUNT: 10 INVOICE: 30
---	--	--	--	--



Total Vehicles Cost TODAY: 10 WEEK: 20 MONTH: 30	Today Service Capacity/Occupancy TODAY: 10 WEEK: 20 MONTH: 30
Service Occupancy Rate DAY: 10 MONTH: 20 YEAR: 30	Service Area Wise Occupancy(%) TODAY: 10 WEEK: 20 MONTH: 30

Totals: 73 Service Yet To Start: 0 Service In Progress: 2 Ready for Delivery: 71 Srch Veh NO: 0 <Age-6< 73 Reset

Not Started	In Progress	Ready For Delivery																																																																					
No data	AP31EM44688 AP31EM1880	<table border="1"> <tr><td>AP31EM4466</td><td>AP31AP0007</td><td>AP31D2345</td></tr> <tr><td>AP31EM0001</td><td>AP31D3456</td><td>AP31K5247</td></tr> <tr><td>AP35S07894</td><td>AP39UW7095</td><td>AP31D2547</td></tr> <tr><td>AP31D5827</td><td>AP31K7890</td><td>AP31CR1123</td></tr> <tr><td>AP39AK2294</td><td>AP39G08538</td><td>AP97DD3424</td></tr> <tr><td>AP39US4584</td><td>ODDZM1881</td><td>AP31BP3676</td></tr> <tr><td>AP39GV7859</td><td>AP39K24962</td><td>AP31H2547</td></tr> <tr><td>AP31PA9990</td><td>AP31EM4446</td><td>AP31EM4469</td></tr> <tr><td>AP31EM4460</td><td>AP31EM0009</td><td>AP35SR5555</td></tr> <tr><td>AP35SR9999</td><td>AP31BA2345</td><td>AP31BP3676</td></tr> <tr><td>AP05SR7173</td><td>AP69WW6969</td><td>AP00SR0005</td></tr> <tr><td>AP35PL4336</td><td>AP31AP0055</td><td>AP31AP0089</td></tr> <tr><td>AP31KA1234</td><td>AP11SR1111</td><td>AP09SR0909</td></tr> <tr><td>USA2024-1</td><td>AP16DM2323</td><td>USAVH1002</td></tr> <tr><td>AP313107</td><td>AP09SR9999</td><td>AP31EM888</td></tr> <tr><td>AP39KA2717</td><td>AP31EM6789</td><td>AP31RZ7654</td></tr> <tr><td>AP31EM0101</td><td>AP12SR4000</td><td>AP31L01234</td></tr> <tr><td>BLK2722</td><td>AP73SR7373</td><td>AP73SR5555</td></tr> <tr><td>TR56TR5656</td><td>SR05CH5555</td><td>AP73SR7337</td></tr> <tr><td>AP39SN4555</td><td>BLK2722</td><td>LKP6565</td></tr> <tr><td>AP07SR0007</td><td>DR55DT5555</td><td>CH73SR7373</td></tr> <tr><td>AP31AP1111</td><td>APW11023</td><td>INE11000</td></tr> <tr><td>AP31AW0001</td><td>AP31KA2717</td><td>AP07SR7373</td></tr> </table>	AP31EM4466	AP31AP0007	AP31D2345	AP31EM0001	AP31D3456	AP31K5247	AP35S07894	AP39UW7095	AP31D2547	AP31D5827	AP31K7890	AP31CR1123	AP39AK2294	AP39G08538	AP97DD3424	AP39US4584	ODDZM1881	AP31BP3676	AP39GV7859	AP39K24962	AP31H2547	AP31PA9990	AP31EM4446	AP31EM4469	AP31EM4460	AP31EM0009	AP35SR5555	AP35SR9999	AP31BA2345	AP31BP3676	AP05SR7173	AP69WW6969	AP00SR0005	AP35PL4336	AP31AP0055	AP31AP0089	AP31KA1234	AP11SR1111	AP09SR0909	USA2024-1	AP16DM2323	USAVH1002	AP313107	AP09SR9999	AP31EM888	AP39KA2717	AP31EM6789	AP31RZ7654	AP31EM0101	AP12SR4000	AP31L01234	BLK2722	AP73SR7373	AP73SR5555	TR56TR5656	SR05CH5555	AP73SR7337	AP39SN4555	BLK2722	LKP6565	AP07SR0007	DR55DT5555	CH73SR7373	AP31AP1111	APW11023	INE11000	AP31AW0001	AP31KA2717	AP07SR7373
AP31EM4466	AP31AP0007	AP31D2345																																																																					
AP31EM0001	AP31D3456	AP31K5247																																																																					
AP35S07894	AP39UW7095	AP31D2547																																																																					
AP31D5827	AP31K7890	AP31CR1123																																																																					
AP39AK2294	AP39G08538	AP97DD3424																																																																					
AP39US4584	ODDZM1881	AP31BP3676																																																																					
AP39GV7859	AP39K24962	AP31H2547																																																																					
AP31PA9990	AP31EM4446	AP31EM4469																																																																					
AP31EM4460	AP31EM0009	AP35SR5555																																																																					
AP35SR9999	AP31BA2345	AP31BP3676																																																																					
AP05SR7173	AP69WW6969	AP00SR0005																																																																					
AP35PL4336	AP31AP0055	AP31AP0089																																																																					
AP31KA1234	AP11SR1111	AP09SR0909																																																																					
USA2024-1	AP16DM2323	USAVH1002																																																																					
AP313107	AP09SR9999	AP31EM888																																																																					
AP39KA2717	AP31EM6789	AP31RZ7654																																																																					
AP31EM0101	AP12SR4000	AP31L01234																																																																					
BLK2722	AP73SR7373	AP73SR5555																																																																					
TR56TR5656	SR05CH5555	AP73SR7337																																																																					
AP39SN4555	BLK2722	LKP6565																																																																					
AP07SR0007	DR55DT5555	CH73SR7373																																																																					
AP31AP1111	APW11023	INE11000																																																																					
AP31AW0001	AP31KA2717	AP07SR7373																																																																					



SERVICE AREA ANALYSIS DASHBOARDS

Total Service Areas/Working/Idle

Total: 10
Working: 6
Idle: 4

Average Service Completion Time

Today: 10
Overall: 20

SLA Crossed Vehicles

Count: 4

Top 5 SLA VS Actual Completion

Service Areas To be Idle in Next One Hour

Count: 10

Total Labour/Parts/Service Cost

Labour Cost: 10
Parts Cost: 6
Service Cost: 4

Current No of Vehicles Under Unit

Count: 73


Service Area	TrackXServiceArea	TrackXServiceArea002	TrackXServiceArea003	TrackXServiceArea004	TrackXServiceArea005	TrackXServiceArea006
Start Time/Current Efficiency	11:30/85%	10:00/90%	09:00/88%	08:30/92%	12:00/80%	07:45/89%
Targeted/Assigned/Completed(% of completion)	10/8 (80%)	12/11 (92%)	15/13 (87%)	8/8 (100%)	9/7 (78%)	14/12 (86%)
Total Service Time/Idle Time(Today)	200h:40m/50h	220h:50m/40h	250h:30m/60h	180h:20m/30h	210h:15m/55h	240h:25m/45h
No of Completed Job Cards/Day/Week/Month	2/10/40	3/12/48	4/15/60	2/8/32	3/9/36	4/14/56
Work Rate/Day/Week/Month	5h/35h/140h	6h/42h/168h	7h/49h/196h	4h/28h/112h	6h/36h/144h	7h/49h/196h
Exp.Free Time	2h	1.5h	2.5h	1h	3h	2h
Complaint Analysis(Low/High)	Compl1 - 100%	Complaint2 - 100%				
SLA Crossed Vehicles Count	1	0	2	1	3	2

S.No	Service Car	Start-Time Exp	Start-Time	Complaints	% of Completion	SLA	Worked Time	Remaining Time	Labour Cost	Spare Parts Cost	Total Service Cost	Status

Services Count Today : 0 Month : 30 Year : 73	Waiting to start Service / Under service 0/2	Invoice Pending Service Count / Amount 71 / ₹ 0	Service Count / Total Invoice Raised 0 / ₹ 0
Total Vehicles 73	Total active Services / Completed 0 / 0	Total Parts Cost ₹ 0	Total labour cost / Total service cost 0/0

	Parking Area	Work Shop	Washing	Dis
Inprogress	2	2	1	
Completed	32	29	28	
Total	34	31	29	

D1130820240001 AP31EM44688 Eshwar	Arrived 16 16 14-08-2024	Duration 00 03	Check-out 16 20 14-08-2024	Arrived - -	Duration - -	Check-out - -	Arrived - -
D1140820240001 AP31EM1880 White	Arrived 16 56 14-08-2024	Duration 00 09	Check-out 17 05 14-08-2024	Arrived 17 05 14-08-2024	Duration 00 06	Check-out 17 12 14-08-2024	Arrived 17 12 14-08-2024



Model:
Chassis No:
Reg No: **AP31AP00055**

Eshwar
9246649070

Current Service

ServiceId: D1260720240005
Advisor: gnamnesh
FuelStart: 53
FuelEnd: 53

Previous Service Visits

21-08-2024

Customer Name: Eshwar

Odo Meter Reading at start: 2512
Odo Meter Reading at end:

FuelReading at start:
FuelReading at end:

Parking Area

Complaint:
InTime:
OutTime:
Cost: 0

Work Shop

Complaint:
InTime:
OutTime:
Cost: 0

Washing

Complaint:
InTime:
OutTime:
Cost: 0

Dispatch Area

Complaint:
InTime:
OutTime:
Cost: 0